ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 3 | Atturu |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0627, W0629, W0635, W0637, W0641, W0330, W0645, W | NA, 1st Crs, 6th Crs, 2nd Crs, 4th Crs | Akshayanagara area |
| **Segment No.** | **Total Length (m)** | |
| 3/C-W0627/S091012 | 584.77 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 141.92 | 77.564472 | 13.099902 | 77.564923 | 13.101106 | W0330 | DEAD END |
| 2 | 126.62 | 77.564158 | 13.099989 | 77.564542 | 13.101070 | W0330 | DEAD END |
| 3 | 93.53 | 77.563933 | 13.100281 | 77.564199 | 13.101085 | DEAD END | DEAD END |
| 4 | 83.92 | 77.563630 | 13.100341 | 77.563864 | 13.101064 | DEAD END | DEAD END |
| 5 | 138.78 | 77.563837 | 13.100861 | 77.565065 | 13.100532 | W0627 | W0649 |

## Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Construction of Culvert and Improvements of Drains in Akshayanagara area in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone | 2000000 | 2014 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2014 - 2015 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Construction of Culvert and Improvements of Drains in Akshayanagara area in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone | 003-15-000013 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE (YNK.D) E-PMT-4/WO/38/2014-15 | 08/01/2015 | 90 DAYS |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 31/01/2015 | 30/01/2016 | Yes |

## Contractor Details

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0627, W0629, W0635, W0637,

ABE

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| M B HOMBAL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9900083697 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 10 | | PRADEEP |
| **Date of Inspection** | **Remarks** | |
| 16/01/2017 | COMPLETED | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

Zone: YELAHANKA Ward No: 3 Ward Name: Alluru Street ID: W0627, W0629, W0635, W0637,

ABE

| | | |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

**Remarks**

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | PARAMESHWARAIAH | 16/01/2017 | 15/02/2017 | COMPLETED |
| SE | VASU K M | 16/01/2017 | 15/02/2017 | COMPLETED |
| EE | VASU K M | 16/01/2017 | 15/02/2017 | COMPLETED |
| AEE | ASHOK | 16/01/2017 | 15/02/2017 | COMPLETED |
| AE | PRADEEP | 16/01/2017 | 15/02/2017 | COMPLETED |
| AE | PRADEEP | 16/01/2017 | 15/02/2017 | COMPLETED |

**Zone:** YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0627, W0629, W0635, W0637,

ABE